

**REVISED LIST OF E&M CENTRALISED**

<b>SI No</b>	<b>Description</b>
1	Ms Pipe/ GI pipes of all sizes.
2	Conveyor belt Rubber / PVC/Steel Cord etc. all sizes.
3	Haulage Wire Rope/ Winding Rope/Guide Rope/Engg Wire Rope of all sizes.
4	Power/ Trailing Cables (Both A1 Copper)/ Telephone cable of all sizes.
5	All sizes and types of Aluminium Conductors/ ACSR/ AAAC conductors.
6	All sizes and types of Poles (Steel Tubular & Rail Poles).
7	Chain & Flight Assemblies, Drive Head Assy., Gear Box Assemblies for use of LDCC/MDCC/ HS-6 chain conveyors.
8	All Types & sizes of reduction Gear Box Assemblies used in Belt Conveyors, Reciprocating Feeders, Crushers, Apron Feeders and vibrating screen of CHPs.
9	All types and sizes / rating of Motors like L.T. Motors, H.T. Motors (squirrel Cage/ Slip Ring Motors) used in CHP drives, Belt Conveyors, Pumps, Direct/ Endless Haulages, Tugger Haulages and Motors required for other mining equipments.
10	Major CHP items like:-
	a) Crusher Drum Assembly.
	b) Roll Crushing Assembly.
	c) Reduction Gear Box for Crusher.
	d) Drive Assembly for all types / sizes of Belt Conveyors.
	e) Complete vibrating Screen / Reciprocating Feeders/ Crizzley Scscreens.